

Supplement

Title: 700HTP-2 I.S. Supplement Issue: 1
Part Number: 4096896 Issue Date: 3/12
Print Date: Sept. 2011 Page Count: 1
Revision/Date:

This supplement contains information necessary to ensure the accuracy of the above Instruction Sheet.

Change #1

Under ***Replacement Parts***,

Change: Handle Assembly Rebuild Kit, Fluke PN
2844352

To: Handle Assembly Rebuild Kit, Fluke PN
3668409